

2020 VOLKSWAGEN T-Cross

Reg: SAMPLE

Motoring Centre: Auckland Mobile Inspections (0800 500 333, Option 1)
Inspection Date: 11 Nov 2020
Mobile Inspection: Yes

Inspection Report No.:

991558

REPORT OWNER

Name: SAMPLE
Address: 39, Sample Road, Albany
Email:

Membership Number:
Contact Phone: 123456
Mobile: 123456

VEHICLE DESCRIPTION

Odometer: 5555	Chassis:	Engine Size: 1.0
Origin: New Zealand New	VIN: SAMPLE-V1N-NUMBER	No. of Cyls: 3
* WOF Expiry:	Colour:	Transmission: Automatic
Reg Expiry:	Seating:	Drive Train: Front Wheel Drive
RUC Expiry:	Body Type: SUV, Five Door	Fuel: Petrol
First Reg NZ:	ESC / ESP:	Engine Fuel System: Turbocharged: Fuel Injected

* It is a legal requirement that a Warrant of Fitness be less than one month old when a vehicle is sold.



Front and Side



Interior



Rear and Side



Engine or Interior 2

REPORT SUMMARY

VEHICLE CONDITION SUMMARY For a used vehicle, in good condition consistent with age and mileage, unlikely to require unplanned maintenance or repair:

Inspector Comments

ITEMS COVERED BY THIS INSPECTION

Braking System

- 1 ABS
- 2 Parking Brake
- 3 Hose Assembly
- 4 Master Cylinder
- 5 Pedal
- 6 Pipe Assembly
- 7 Proportioning Valve
- 8 Road Test
- 9 Vacuum Pump
- 10 Wheel Assembly

Cooling System

- 11 Radiator
- 12 Water Pump (Where Visible)
- 13 Oil Cooler
- 14 Thermostat
- 15 Management

Driveline

- 16 Driveshaft
- 17 Differential

Electrical

- 18 Battery
- 19 Lighting
- 20 Starter
- 21 Ignition
- 22 Alternator
- 23 Instruments
- 24 Horn
- 25 Accessories
- 26 Wiring
- 27 Window Assembly
- 28 Switch Assembly

Engine

- 29 Air Filter
- 30 Noise

Engine

- 31 Roadtest
- 32 Assembly
- 33 Lubrication
- 34 Tappet Cover
- 35 Valley Cover
- 36 Side Cover
- 37 Sump
- 38 Timing Cover
- 39 Bellhousing
- 40 Head
- 41 Block
- 42 Mounting
- 43 Super Charger
- 44 Turbo Charger
- 45 Intercooler
- 46 Management System
- 47 Breather hose

Entrance and Exit

- 48 Door Assembly
- 49 Hatch Assembly
- 50 Bonnet Assembly

Exhaust System

- 51 Assembly
- 52 Road Test

Fuel System

- 53 Tank
- 54 Hose Assembly
- 55 Pipe Assembly
- 56 Filter
- 57 Pump
- 58 Injector
- 59 Carburettor

Fuel System

- 60 Alternate Fuel
- 61 Management
- 62 Choke

Heating and Ventilation

- 63 Air Conditioning
- 64 Heater

Interior

- 65 Boot
- 66 Tools and Accessories
- 67 Dashboard
- 68 Seat
- 69 Cabin Ancillaries
- 70 Cargo Bay
- 71 Roof
- 72 Seat Belt
- 73 Spare Wheel Compartment

Miscellaneous Items

- 74 Accessories

Road Test Conditions

- 75 Tested Speed
- 76 Conditions

Steering

- 77 Box
- 78 Bevel Box
- 79 Column
- 80 Drag Link
- 81 Drop Arm
- 82 Idler
- 83 Power Assist
- 84 Rack
- 85 Road Test
- 86 Tie Rod
- 87 Wheel
- 88 Universal Joint

Steering

- 89 Stop

Structure

- 90 Body Assembly
- 91 Chassis

Suspension

- 92 Axle
- 93 Spring Assembly
- 94 Shock Absorber
- 95 Control Arm
- 96 Radius Rod
- 97 Strut Bar
- 98 Trailing Arm
- 99 Anti Sway Bar
- 100 Anti Sway Bar Link
- 101 Watts Link
- 102 Panhard Rod
- 103 Road Test

Towing Connections

- 104 Tow Bar

Transmission

- 105 Assembly

Tyres Wheels and Hubs

- 106 Hub
- 107 Tyre
- 108 Wheel

Vision

- 109 Rear View Mirror
- 110 Sun Visor
- 111 Windscreen Wiper
- 112 Windscreen Washer
- 113 Glazing



OK



Not Applicable



Potential WoF defects requiring urgent attention



Defects requiring further investigation or repair




Other items, keep under observation

No Damage Identified

Need Mechanical Breakdown Insurance? Visit aa.co.nz/mbi


BODY CONDITION AND COMMENTS




1

Bodywork in good condition, no defects noted.

INTERIOR CONDITION AND COMMENTS




TYRE CONDITION



Legal Minimum 1.5mm for Standard Tyres, 4mm for Snow Tyres

12v ELECTRICAL SYSTEM TEST



Good test results, no action required.

Additional Information

Head Gasket Test: OK, Passed, No combustion gasses detected

Has Timing Belt: No

Air Conditioning Test Results: -5 degrees C measured at the dash vent

Heater Test Results: 38 degrees C measured at the dash vent

Test Speed Range: 40-50 km/h

Road Test Conditions: Dry

Modified Vehicle: No: