## SERVICE MENU

All items include labour and GST



## Auto Centre

| ENGINE OIL REQUIREMENT  | TIER       | AA BRONZE<br>SERVICE TM | AA SILVER SERVICE TM | AA GOLD SERVICE TM | NOT AN AA MEMBER?  STANDARD OIL, SILVER SERVICE AND A 12 MONTH  AA MEMBERSHIP FOR ONLY \$338  Terms & conditions apply.  |
|---|------------|-------------------------|----------------------|--------------------|--|
| STANDARD OIL PETROL, DIESEL & HYBRID INCLUDES:                  | AA MEMBER  | \$239                   | \$269                | \$329              | AA EV SERVICE FROM \$149 M - FROM \$169 NM   |
| 4.5L Standard Oil<br>\$30 RRP Oil Filter<br>500ml Fluid Top Ups | NON MEMBER | \$259                   | 50 Maria \$299       | \$369              | Wof INSPECTION FROM \$73** M - FROM \$82** NM  |
| ADVANCED OIL PETROL, DIESEL & HYBRID INCLUDES:                  | AA MEMBER  | \$319                   | \$349                | \$409              | AA PRE PURCHASE INSPECTION FROM \$184 M - FROM \$209 NM  |
| 6L Synthetic Oil<br>\$50 RRP Oil Filter<br>500ml Fluid Top Ups  | NON MEMBER | \$339                   | \$379                | \$449              | AA MEMBERSHIP \$99 AUCKLAND - \$89 REST OF NZ  **\$10 premium applies to selected locations   M = MEMBER NM = NON MEMBER |
|   | INCINIULA  |                         |                      | 444                |  |

STANDARD OIL PETROL, DIESEL & HYBRID SERVICE includes up to 4.5 litres of mineral or\* semi synthetic engine oil, \$30 RRP oil filter and up to 500ml of additional fluid top-ups.

\*Selection of oil is at AA Auto Centre's sole discretion and is based on the Original Equipment Manufacturer specifications.

ADVANCED OIL PETROL, DIESEL & HYBRID SERVICE includes up to 6 litres of standard synthetic engine oil, \$50 RRP oil filter and up to 500ml of additional fluid top-ups.

Additional charges may apply for additional oil, speciality oil, oil filters over the RRP amounts and vehicles that require further labour to inspect. In these situations these costs will be discussed with you.

AA EV SERVICE fluid levels found to be low may require further labour to inspect and topping up as required. This will be discussed with you and may incur additional charges.

