

Vehicle Appraisal

2002 HONDA CIVIC VI

Reg: TEST

This appraisal has been prepared by the New Zealand Automobile Association acting as a technical consultant for the Motor Vehicle Dealer named below and not for any prospective purchaser of the vehicle and as such is performed "In Trade" under the Consumers Guarantees Act. The Appraisal to which this report refers is external and visual only and of necessity does not include defects or conditions of internal mechanisms that may be discovered by subsequent dismantling. The report applies to the condition of the vehicle at the time of appraisal.

Purchasers could obtain greater protection from a full AA Vehicle Inspection

Vehicle Inspection Centre: Test Branch 2 **11787958**
This report has been carried out for: THE HOUSE OF CARS
 270, Main Road, Your Town

Appraisal Date: 17-May-2012

Reg Expiry: 22-Jun-2012

VIN Number: 7ATLDKR76O8428766

Expiry Date: 17-Jul-2012

WOF: 13-Jul-2012

Origin: New Zealand New

Odometer: 58264 Kms

RUC: Expiry:

Year First Reg: 2002

Items Covered By This Inspection

Brake System Visual External Only

- 1 Brakes
- 2 Brakes - Under Body

Cooling System

- 3 Radiator
- 4 Water Pump (Where Visible)

Electric Accessories / Lamps

- 5 Lamps

Electrical

- 6 Battery
- 7 Horn

Engine Ancillaries

- 8 Lubricants (Eng/Trans)
- 9 Engine
- 10 Fuel System
- 11 Air Filter

Engine Audible Noises

- 12 Engine Noise

External Items

- 13 Rear View Mirror
- 14 Windscreen Wiper
- 15 Windscreen Washer
- 16 Ancillary Items

Fuel System

- 17 Fuel Filler

Interior

- 18 Tools and Accessories

Road Test

- 19 Engine Test
- 20 Transmission Test
- 21 Exhaust Test
- 22 Steering Test
- 23 Foot Brake Test
- 24 Handbrake Test
- 25 Air Conditioning

Suspension

- 26 Suspension
- 27 Wheels
- 28 Hubs


Tyres

- 29 Tyres

Underside


- 30 CV Joints
- 31 Structure
- 32 Steering - Under Body
- 33 Transmission
- 34 Driveshaft
- 35 Axle
- 36 Differential
- 37 Engine
- 38 Exhaust

Tread Depths



Legal Minimum 1.5mm for Standard Tyres,
4mm for Snow Tyres

Relative Compression Test



Relative Compression Reading

Relative compression readings acceptable for age and mileage of vehicle

Defects Found During Inspection

CV Joints	Left Hand Front CV Boot: Leaking grease, Not correctly located
Tools and Accessories	Toolkit: Missing
Wheels	Left Hand Front Rim: Damaged
Windscreen Wiper	Front Blade: Worn

General Comments

Presentation: Appraisal: Satisfactory: In average condition for age and mileage