

2010 TOYOTA Vanguard

Reg: XXXXXX

This appraisal has been prepared by the New Zealand Automobile Association acting as a technical consultant for the Motor Vehicle Dealer named below and not for any prospective purchaser of the vehicle and as such is performed "In Trade" under the Consumers Guarantees Act. The Appraisal to which this report refers is external and visual only and of necessity does not include defects or conditions of internal mechanisms that may be discovered by subsequent dismantling. The report applies to the condition of the vehicle at the time of appraisal.

Purchasers could obtain greater protection from a full AA Vehicle Inspection

Vehicle Inspection Centre: Auckland Mobile Inspections

00000000

This report has been carried out for: Generic Motors
101 Main Road, Auckland

Inspection Date: 7 May 2021

Reg Expiry: 14 Sep 2021

VIN: XXXXXXXXXXXXXXXXXXXX

Expiry Date: 7 Jul 2021

WOF: 5 Mar 2022

Origin: Import

Odometer: 82897

RUC Expiry:

Year First Registered: 2010

Items Covered By This Inspection As Applicable

Brake System Visual External Only

- 1 Brakes
- 2 Brakes - Under Body

Cooling System

- 3 Radiator
- 4 Water Pump (Where Visible)

Electric Accessories / Lamps

- 5 Lamps

Electrical

- 6 Horn
- 7 Battery

Engine Ancillaries

- 8 Lubricants (Eng/Trans)
- 9 Fuel System
- 10 Engine
- 11 Air Filter

Engine Audible Noises

- 12 Engine Noise

External Items

- 13 Rear View Mirror
- 14 Windscreen Wiper
- 15 Windscreen Washer
- 16 Ancillary Items

Fuel System

- 17 Fuel Filler

Interior

- 18 Tools and Accessories

Road Test

- 19 Engine Test
- 20 Transmission Test
- 21 Exhaust Test
- 22 Steering Test
- 23 Foot Brake Test
- 24 Handbrake Test
- 25 Air Conditioning

Suspension

- 26 Suspension
- 27 Wheels
- 28 Hubs


Tyres

- 29 Tyres

Underbody


- 30 Components
- 31 Steering
- 32 Steering - Under Body
- 33 Transmission
- 34 Driveshaft
- 35 Axle
- 36 Differential
- 37 Engine
- 38 Exhaust

Tyre Condition



Legal Minimum 1.5mm for Standard Tyres, 4mm for Snow Tyres

12v ELECTRICAL SYSTEM TEST



Good test results, no action required.

Defects Found During Inspection

General Condition

Sound : Vehicle is in above average condition for age and mileage